


SECRET



17 JUL 1962

MEMORANDUM FOR: Chief, Office of Special Activities/DDR

ATTENTION :

SUBJECT :

Technical Evaluation of Mission 3084

1. The HEPC evaluation of this mission was made from the original recordings.

2. Performance of Recording Equipment:

The slave recorder did not operate at the proper speed during the reconnaissance. The tape velocity was, as a result, excessive and erratic.

3. Performance of Receiving Equipment:

a. [] The receiver functioned in a satisfactory manner.

b. [] No data associated with this receiver appeared on the recording and it is assumed that the receiving system was inoperative.

c. [] This receiver functioned properly.

d. [] The receiver performed satisfactorily.

**Acting Chief
Elint & Special Projects Division**

Distribution:

Orig & 1 - Addressee

1 - OSA/Intel/DDR

1 - SPB/OSA/DDR

2 - ESPD/SI

2 - DPB/ESPD/SI

25 YEAR RE-REVIEW